

Snagged cargo carrying unit during offshore discharge

Safety Flash Published on 29 February 2012 Generated on 14 January 2025 IMCA SF 02/12

The MSF published Safety Flash 12-07 regarding an incident in which, during a 'routine' cargo discharge operation, the corner stacking point on a skip snagged on the top of one of the vessel's safe haven openings.

What happened?

This resulted in a 21 tonne overload on the platform's crane and damage to the skips lifting bridle and stacking point.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).