

### WSH: fatality – worker crushed by engine piston assembly

Safety Flash Published on **5 February 2015** Generated on **28 January 2026** IMCA SF 02/15

The Workplace Safety and Health Council of Singapore has published a safety flash regarding an incident in which a worker was fatally crushed by a piston assembly within the engine room of a marine vessel docked at a shipyard.

The accident occurred during engine overhaul works. During the installation of the piston assembly, a worker entered the crank case to carry out alignment work. While doing so, the piston assembly suddenly fell, crushing the worker who was positioned directly beneath the assembly. He was immediately extricated by fellow workers and sent to the nearest hospital, where he succumbed to his injuries about two hours later.

*IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.*

*The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.*

*All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.*

*IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.*

*The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.*

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).