

UK MAIB: Deep fat fryer fire

Safety Flash Published on 22 January 2024 Generated on 23 January 2025 IMCA SF 02/24

The supply breaker to the deep fat fryers tripped while the equipment was heating up and the engineers were called to reset it.

The UK Marine Accident Investigation Branch published [Safety Digest 2/2023](#), consisting of lessons from recent Marine Accident Reports. IMCA has reviewed the report and passes on to members some of the incidents in the MAIB report. This is one of them.

What happened?

Catering crew had a lucky escape after switching on the galley equipment electrical isolators to start preparing for lunch. The supply breaker to the deep fat fryers tripped while the equipment was heating up and the engineers were called to reset it.

Two of the deep fat fryers had no oil in them and their heating elements quickly overheated when the power supply was restored after the breaker was reset. The ship's alarm and monitoring system detected the excessive temperatures and the thermal protection tripped the deep fat fryers' power supply, but not before a fire had started.

The crew raised the alarm and used a fire blanket to quickly smother the flames. The ship's emergency team mustered, isolated the galley's power and ventilation supplies and confirmed the fire was successfully extinguished. There was no damage and no injuries.

What went wrong?

The two deep fat fryers had been drained of oil for cleaning and the cause of the fire was found to be residual food scraps saturated with fat that had ignited when the fryers were switched on.

Lessons learned

- Ensure lock-out/tag-out (LOTO) procedures are fit for purpose and followed fully during maintenance and cleaning tasks.
 - Displaying a simple do not use notice on out of service equipment can improve safety and prevent careless mistakes
- Ensure equipment is ready to go back into service when work has been completed.

- Check circuit breakers, trip switches and fuses, which prevent electrical systems becoming overloaded or causing harm. Always check equipment before resetting its electrical supply to ensure all is well.
- Drills: robust safety procedures and well-practised drills prepare crew to deal with the unexpected. In this case the rapid organised response to a small fire prevented injury to crew and serious damage to the ship.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).