

DSI air helmets – Leakage of water into regulator

Safety Flash Published on 1 June 2002 Generated on 16 March 2025 IMCA SF 04/02

We received a safety flash yesterday from Divex Ltd, who are distributing the information to all potential users, who should fully check and test their equipment to ensure continued safe usage and operation.



Divex Ltd.
Enterprise Drive
Westhill, Aberdeen
AB32 6TQ, United Kingdom
Telephone +44 (0)1224 740145
Facsimile +44 (0)1224 740172
e-mail info@divex.co.uk

DIVEX CAUTION/SAFETY NOTICE

Safety Notice No. DVX001/2002

DSI AIR HELMETS

DIVEX LTD HAVE BECOME AWARE OF A POTENTIAL PROBLEM WITH LEAKAGE INTO THE REGULATOR ON DSI HELMETS.

Divex Ltd would advise all users of KMBDSI air helmets that we have been informed of a potential problem with leakage of water into the following air diving helmets and bandmasks through the mushroom valve.

TYPE			
"	DE028	Exhaust Mushroom valve	KMDSI part # 510-552
"	DE055	Kirby Morgan 18B Bandmask	KMDSI part # 500-026
"	DE056	Kirby Morgan 17B Helmet	KMDSI part # 500-011
"	DE1121	Kirby Morgan 17B Helmet	KMDSI part # 500-010
"	DE1141	Kirby Morgan 18B Bandmask	KMDSI part # 500-025
"	DE1101	Kirby Morgan 28B Bandmask	KMDSI part # 500-029
"	DE128	Kirby Morgan Regulator Kit	KMDSI part # 525-309

It would appear that water is entering the regulator on the above detailed helmets through the mushroom valve in the regulator. Divex, who are in contact with the manufacturer, is undertaking the investigation into the reason for this failure at this time. It is envisaged a definitive conclusion will be available within the next week (by 20th June 2002).


Divex Ltd has produced this notice to ensure all users of these helmets fully check and test their equipment to ensure continued safe usage.

The information available to date is that all helmets, with mushroom valves detailed above, that carry numbering may be suspect. Mushroom valves that are not numbered, are at this time considered fit for purpose. The numbering can be found moulded into the mushroom valve.

This is all the information available. This notice will be followed up with a final notice when more information becomes available.

In the interest of safety, I am sure that you will agree with the Divex Ltd action to distribute this notice as early as possible, even though a full detailed investigation has not been completed.

For further information contact Kathleen Scanlan on the above telephone or fax number. Alternatively e-mail to safety@divex.co.uk



SIGNED _____ DATED: 14th June 2002
G. T. Gilbert, For and on behalf of Divex Ltd.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).