

Snagging damage during lifting operations

Safety Flash Published on 8 June 2012 Generated on 20 January 2025 IMCA SF 05/12

The Marine Safety Forum (MSF) published Safety Flash 12-13 regarding an incident in which part of a platform supply vessel was damaged when a large piece of equipment was lifted off it onto an offshore installation.

What happened?

The load being lifted snagged on a walkway and caused the damage. The root cause of the incident was that the lift plan and risk assessment failed to identify all the hazards involved.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).