

MODU mooring line failure

Safety Flash Published on 4 September 2024 Generated on 14 January 2025 IMCA SF 09/12

The Marine Safety Forum (MSF) published Safety Flash 12-31 regarding an incident in which a MODU mooring line failed.

What happened?

The line was one of eight mooring lines for the MODU, which was involved in drilling at the time. The MODU moved some 12m and tilted 2-3 degrees but was restored to the correct position using thrusters and ballasting.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).