

Dynamic positioning (DP) system failure

Safety Flash Published on 1 November 2011 Generated on 28 January 2026 IMCA SF 12/11

IMCA has received information from a Member about an incident involving the DP system aboard one of its vessels.

Because of the resulting inherent failure possibility, the company has identified the need to modify the software installed in the DP systems on several vessels within its fleet.

The DP manufacturer has issued a [technical bulletin](#) about this.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).