

Engine room fire on offshore vessel

Safety Flash Published on 1 November 2011 Generated on 3 July 2025 IMCA SF 12/11

The Marine Safety Forum (MSF) has published Safety Flash 11-32 regarding a fire reported in the main engine room of an offshore support vessel which was under tow at the time.

The source of the fire was identified as being fuel oil leaking from the flange on a fuel injector pump onto an engine.

Further information about this can be found [here](#).

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).