

Poor condition of lifting strops

Safety Flash Published on 23 December 2011 Generated on 12 January 2025 IMCA SF 14/11

The MSF has published Safety Flash 11-39 regarding lifting strops found in poor condition.

Recent audits/inspections have highlighted deficiencies with regards the state of lifting strops which were found to be in a severely deteriorated condition, unfit for purpose and still in service onboard.

The complete safety flash is available [on request](#) from the Marine Safety Forum.

Members are also referred to *Guidelines for lifting operations*.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).