

## MSF: Bulk hose entanglement with Azi-pod propulsion unit

Safety Flash Published on 12 September 2013 Generated on 18 February 2026 IMCA SF 14/13

The Marine Safety Forum has published safety flash 13-26 regarding an incident in which a hose became entangled with an Azi-pod propulsion unit.

The incident occurred during preparations to deliver water to a platform. It was decided to use the aft manifold connection on the starboard quarter for the water transfer, and two ABs were standing by ready to connect the hose.

After being lowered by the crane, the hose was observed to sink in the water close to the stern cut-away, under which the Azi-pod units are mounted.

Details of the incident are now available [on request](#) from the Marine Safety Forum.

*IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.*

*The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.*

*All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.*

*IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.*

*The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.*

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).