

MSF: Injury – Failure of hatch holdback arrangements

Safety Flash Published on 23 September 2013 Generated on 14 January 2025 IMCA SF 15/13

The Marine Safety Forum has published safety flash 13-32, regarding an incident in which a crew member was injured when there was a failure of the mechanism holding back a heavy watertight door.

The incident occurred because the arrangements for holding back the door were not adequate.

Full details of the safety flash are available [on request](#) from the Marine Safety Forum.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).