# Service bulletin – integrated flywheel generators (IFGs)

Safety Flash Published on **25 February 2011** Generated on **28 January 2026** IMCA SF 02/11

**A Member recently reported an electrical fire inside its self-propelled hyperbaric lifeboat (SPHL).**

Service Bulletin 2010IWP091 (issued by Steyr Motors) was distributed to users at the request of Oceanwide Safety at Sea.

Users of SPHLs using Steyr Motors' integrated flywheel generators (IFGs) should review the service bulletin here.

*IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.*

*The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.*

*All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.*

*IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.*

*The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.*

*Share your safety incidents with IMCA online. Sign-up to receive Safety Flashes straight to your email.*