

## Bail-out whip failures

Safety Flash Published on 2 March 2001 Generated on 28 January 2026 IMCA SF 04/01

We have a safety alert from Hydrasun Limited concerning reported failures of 3/8" R6 hose type bail-out whip assemblies.



### Safety Alert

#### BAIL OUT WHIP ASSEMBLIES

##### To whom it may concern

Due to a small number of reported failures on a Hydrasun Ltd manufactured bail out whip assemblies (3/8" R6 hose type) (awaiting return of all failed assemblies for inspection)

It has become a necessity to request you ensure that all additional assemblies of the same type/configuration still in service are required to be inspected/tested prior to use. (Either by Hydrasun Ltd or your own personnel –Guidelines available)

Note if required a comprehensive list of all assemblies purchased can be supplied c/w your order no, date of supply and our unique assembly tag no for each hose to aid assembly identification.

However due to Diving Industry demands a new bail out whip assembly (3/8" 2TE) has been developed with upgraded hose type and fitting attachment method, (Which has passed stringent prototype load/ pressure tests well in excess of its normal application parameters)

The new bail out whip assemblies can be ordered by quoting the following part no

**AY06-015A-955D-BE-ZZ-1.000**

Note: the 2TE bail out whip assembly will supersede the R6 bail out whip assembly, which has ceased to be manufactured.

Please contact Andy Edmond on 01224 618683 if you require any additional information or require assembly list details.

Yours faithfully,

A Edmond  
Q.A.Manager

##### The Hose and Fitting Specialists

HOSE AND FITTINGS TO SUIT HYDRAULIC, INDUSTRIAL AND OILFIELD APPLICATIONS, TUBE FITTINGS & VALVES TO SUIT HYDRAULIC, INSTRUMENTATION AND ULTRA HIGH PRESSURE APPLICATIONS, TUBE CLAMPS, PRESSURE GAUGES, PIPE FITTINGS, PNEUMATIC EQUIPMENT AND VALUE ADDED SERVICES

REG. IN SCOTLAND No: 59688  
REG. OFFICE: 392 KING STREET, ABERDEEN, AB24 3BD

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).

