

## Divex HSE Alert HSE001-2007 – Valve seat retainer

Safety Flash Published on 20 December 2007 Generated on 14 January 2025 IMCA SF 10/07

Divex has asked IMCA to recirculate the attached Divex HSE Alert, first issued in IMCA Safety Flash 02/07 (Divex HSE Alert – Valve seat retainer), in order to ensure companies and their worksites around the world are aware of this issue.

Divex will replace all faulty valve seat retainers. Please advise the Divex Aberdeen sales office of the quantity required. These will be shipped carriage free and invoiced at standard spare part price. Any faulty valve seat retainers returned to Divex Aberdeen quoting the sales order ref we give at time of replacement ordering will be credited at full price.

**NAME:** Malcolm Cattanach **TITLE:** Commercial Projects & **DATE:** 21/02/07  
Products Manager

**for and on behalf of Divex Ltd.**

*The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.*

*All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.*

*IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.*

*The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.*

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).