

Potential dropped object: Inbound cargo

Safety Flash Published on 17 May 2016 Generated on 17 January 2025 IMCA SF 14/16

The Marine Safety Forum (MSF) has published a safety alert regarding a potential dropped object.

What happened?

Back-loading of a large piece of equipment took place from an offshore location. Subsequently on the quayside it was discovered that a steel blanking plate had been stored in the fork-lift pocket of this piece of equipment whilst it had been in service offshore. The unit had been offshore for around two years. This plate had potential to cause serious harm had it fallen out and dropped.



IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfill or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).