DIVEX CAUTION/SAFETY NOTICE

Safety Notice No. <u>DVX001/2002</u>

DSI AIR HELMETS



Divex Ltd.

Enterprise Drive Westhill, Aberdeen AB32 6TQ, United Kingdom

Telephone +44 (0)1224 740145 Facsimile +44 (0)1224 740172 e-mail info@divex.co.uk

DIVEX LTD HAVE BECOME AWARE OF A POTENTIAL PROBLEM WITH LEAKAGE INTO THE REGULATOR ON DSI HELMETS.

Divex Ltd would advise all users of KMBDSI air helmets that we have been informed of a potential problem with leakage of water into the following air diving helmets and bandmasks through the mushroom valve.

TYPF

	DE028	Exhaust Mushroom valve	e K	MDSI part # 510-552
II .	DE055	Kirby Morgan 18B Bandn	nask K	MDSI part # 500-026
II .	DE056	Kirby Morgan 17B Helme	t K	MDSI part # 500-011
II .	DE1121	Kirby Morgan 17B Helme	t K	MDSI part # 500-010
II .	DE1141 Kirby M	lorgan 18B Bandmask	KMDSI pa	rt # 500-025
II .	DE1101 Kirby M	lorgan 28B Bandmask	KMDSI pa	rt # 500-029
II .	DE128	Kirby Morgan Regulator	Kit K	MDSI part # 525-309

It would appear that water is entering the regulator on the above detailed helmets through the mushroom valve in the regulator. Divex, who are in contact with the manufacturer, is undertaking the investigation into the reason for this failure at this time. It is envisaged a definitive conclusion will be available within the next week (by 20th June 2002).

Divex Ltd has produced this notice to ensure all users of these helmets fully check and test their equipment to ensure continued safe usage.

The information available to date is that all helmets, with mushroom valves detailed above, that carry numbering may be suspect. Mushroom valves that are not numbered, are at this time considered fit for purpose. The numbering can be found moulded into the mushroom valve.

This is all the information available. This notice will be followed up with a final notice when more information becomes available.

In the interest of safety, I am sure that you will agree with the Divex Ltd action to distribute this notice as early as possible, even though a full detailed investigation has not been completed.

For further information contact Kathleen Scanlan on the above telephone or fax number. Alternatively e-mail to safety@divex.co.uk

	GHGulbert	
SIGNED	G. T. Gilbert, For and on behalf of Divex Ltd.	DATED: 14 th June 2002