

Date 17 December 2008 Our reference 070206/08/22948

Your date

Your reference

Directorate General of Shipping Joint Director General Walchand Hirachand Marg Ballard Estate Mumbai 400 00 India

Dear Sir,

It has come to the knowledge of the Swedish Maritime Safety Inspectorate that someone is producing counterfeit copies of the Swedish Hammar H20 hydrostatic releases for liferafts. To an untrained eye the copies look almost identical with the original product, with Hammar's logo and address on the labels, but there is, however, one very important difference: the copies do not work.

A ship-owner has recently purchased a number of Hammar H 20 hydrostatic releases from a ship chandler in Mumbai, India. The products came in boxes marked CM Hammar AB, Gothenburg, Sweden. The ship-owner tested the releases and lowered five of them into the water; only one of the hydros actually cut the line. They contacted CM Hammar AB in order to alert the company regarding the malfunction of the releases. The company asked them to return the faulty products, and when they arrived it was discovered that the products were not manufactured by the company. The ship-owner also returned five releases still in their boxes. The company have tested them, and not one worked properly according SOLAS specification (if they worked at all) and the LSA Code 4.1.6.

The Swedish Maritime Administration is very concerned about this situation. There may be a number of ships sailing with counterfeit hydrostatic releases. It is of utmost importance to find out who the manufacturer of these products is, and make him stop production and sale. The only lead to the producer, which the Swedish Maritime Administration has, is that the products were purchased at

INTERNATIONAL SHIPS' STORES SUPPLIERS

101, 'Navratan Building' 69
P.D 'Mello* Road, 1st floor, Carnac Bunder
MUMBAI – 400 009, INDIA

Phone:

91-22-23440057

Fax:

91-22-23439719

We ask for your kind assistance in this matter to obtain, if possible, more information regarding the origin of the counterfeit products. Please, do not

Date 17 December 2008 Our ref 070206/08/22948

hesitate to contact our LSA-expert Roland Eklöf who can be reached at his e-mail address roland.eklof@sjofartsverket.se.

Yours sincerely,

Johan Franson

Director of Maritime Safety

<u>Cc</u>
Pia Berglund
Roland Eklöf
Andreas Holmgren
Jörgen Zachau

CM Hammar AB
Henrik Palsson, Managing Director
August Barks gata 15
SE-421 32 Västra Frölunda
Sweden
Phone +46 (0)31 709 65 51
Mobile +46 (0)706 31 74 45



PRESS RELEASE 2008-12-16 CM HAMMAR, GÖTEBORG, SWEDEN


SAFETY ALERT – DANGEROUS H20 FAKE COPIES!

It has recently come to our attention that someone is producing fake copies of our Hydrostatic Release Unit, the Hammar H20. To an untrained eye, the copy is almost identical to the original product, with Hammar's logo and address on the labels. The fake might look almost like the original product, but there is one very important difference: the copy does not work!

We have tested several of the copies. Not a single one of them worked properly according to SOLAS' specification – the fake H20 will definitely not release a life raft or an Epirb. We see this as a very serious situation. There can be a number of ships at sea that are sailing with fake Hydrostatic Release Units. If any of these ships were to sink, there will definitely be no life rafts or Epirbs that will help to rescue the seafarers in danger!

How can you quickly check that you have the original Hammar H2O?

- Always purchase your products through approved distributors or authorised service points for life rafts and Epirbs
- Make sure that you receive the Hammar multilingual product manual and a raft label with each unit for life raft H20 or Hammar marking instruction for Epirb H20. (Pic 1)
- If you check on the underside of the Hammar H20 you should be able to find 5 (five) fabrication marks on all units produced since April 2006. Units produced before that date have only 2 (two) fabrication marks. (*Pic 2*)
- The serial number and production date can always be verified by contacting CM Hammar at info@cmhammar.
 com. (Pic 2)
- The fabrication mark on the upper side of the unit must always point directly towards the rope. (Pic 3)



If you have any questions regarding this matter please contact us.



Jan Calvert
Sales & Marketing Director
jan.c@cmhammar.com
Direct +46 31 709 65 61
Cell +46 708 49 92 60
www.cmhammar.com