

Bypassing of storage tanks safety features

Safety Flash Published on 4 April 2012 Generated on 14 January 2025 IMCA SF 03/12

The National Offshore Petroleum Safety and Environmental Management Authority of Australia (NOPSEMA) published Alert #50 regarding instances where safety features associated with machinery space oil and fuel tanks have been intentionally bypassed, including deliberately bypassing the spring return valves of tanks containing hydrocarbon inventories by securing them open via a number of means, including zip ties.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).