

## Fatality on the diving support vessel Wellservicer

Safety Flash Published on 9 February 2010 Generated on 25 April 2025 IMCA SF 01/10

**Attached** is a safety flyer issued by the UK Marine Accident Investigation Branch.

### What happened?

The accident was subject to an MAIB investigation and the report is available on the MAIB website ([maib.gov.uk](http://maib.gov.uk)). It is suggested that the flyer should be read in conjunction with the report to fully understand the key learnings to prevent similar incidents occurring in the future.

*IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.*

*The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.*

*All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.*

*IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.*

*The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.*

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).