

## Lower stairwell step collapses causing injury

Safety Flash Published on 4 April 2014 Generated on 20 January 2025 IMCA SF 04/14

The United States Department of the Interior Bureau of Safety and Environmental Enforcement (BSEE) has published the following safety flash regarding an incident in which an injury occurred when a step on a stairwell collapsed causing the worker to fall to the deck and injure his knee.

The safety flash can be downloaded from [here](#).

*IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.*

*The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.*

*All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.*

*IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.*

*The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.*

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).