

## Overloading leads to catastrophic failure of crane boom

Safety Flash Published on 10 April 2014 Generated on 14 January 2025 IMCA SF 05/14

The United States Department of the Interior Bureau of Safety and Environmental Enforcement (BSEE) has published the following safety flash regarding an incident in which a crane boom collapsed after being massively overloaded.

Investigation revealed a number of causes, one being that an incorrect load chart was used at the time of the incident. There were no injuries.

The safety flash can be downloaded [here](#).

*IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.*

*The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.*

*All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.*

*IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.*

*The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.*

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).