

## Unplanned vessel contact with an installation during lifting operations

Safety Flash Published on 17 July 2014 Generated on 28 January 2026 IMCA SF 13/14

**The Marine Safety Forum has published a safety flash regarding an incident in which a vessel made a very slight contact with an installation during lifting operations.**

Only superficial paint damage was caused to the platform and the vessel.

The safety flash report can be requested from [Marine Safety Within The Oil & Gas Industry — Marine Safety Forum](#).

*IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.*

*The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.*

*All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.*

*IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.*

*The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.*

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).