

Injury caused by shifting load of pipes

Safety Flash Published on 12 July 2016 Generated on 28 January 2026 IMCA SF 19/16

The Marine Safety Forum (MSF) has published a safety alert regarding an incident in which a crewman suffered a broken leg.

What happened?

The injury occurred when the crewman got his leg caught under a bundle of pipes that shifted whilst preparing them for a lift. It took fifteen minutes to free the injured crewman, and helicopter medevac ashore was necessary.

IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with [IMCA online](#). Sign-up to receive Safety Flashes [straight to your email](#).